

Projetu MDG's iha Munisípiu Covalima la iha kualidade no balun abandonadu

MDG's Project in Municipal Covalima with poor quality and some of them were abandoned

Projetu Uma MDGS ne'ebe maka governu gasta osan ho montante bo'ot hodi fo ba komonidade sira ne'ebé mak kibít laek liu-liu komoniade Suku Lalawa no suku Belecasac Aldeia Dais munisipiu Covalima la iha kualidade no uma hirak ne'e maioria abandonadu. ne'ebé mak ekipa inspesaun hosi CAC halao deretamente ba iha fatin implementasun mak hanesan:

A CAC team led by Deputy Commissioner José “Sama Larua” Neves had inspected the MDG's house project which government allocated big amount of budget for the benefit of community housing in Lalawa of Tilomar and Dais sub-village of Belecasac village of Covalima Municipal. The team found out that the project is in poor quality and most of the houses are abandoned.

SUKU BELECASAC ALDEIA DAIS

DAIS SUB-VILLAGE OF BELECASAC VILLAGE IN COVALIMA MUNICIPAL

Figure 1 uma sirak ne'e istikador ne'ebé mak hodi istika uma laiha no material ne'ebé mak kompania sobu iha parte plafon nian kompania husik hela deit iha projetu fatin ne'e bele afeta ba benifisiariu sirak ne'ebé mak hela iha uma refere. Fatin Lokaliza iha Suku Belecasac Aldeia Dais.



Photo; these houses rodents that should enhance those houses and materials that company some parts of the houses been dismantle, company has been left them – abandoned in the project place that affected to beneficiary. It happens in Dais sub-village and Belecasac village.

Photo 2; Uma sira ne;e balun abandona hela no moshosi parte balun janela nakfera hotu, fatin lokaliza Suku Belecasac Aldeia Dais



Photo 2; Some of these houses are abandoned and beneficiary are not occupied yet. Some of these houses windows located in Dais sub-village of Belecasac village have broken.

Figure 3. uma sirak ne'e abandona hela no iha ameasa boot wainhira udan boot tamba la iha moru hodi tahan rai. Fatin lokaliza Suku Lalawa



Photo 3; MDGs houses project located in Lalawa village of Tilomar were abandoned and avalanche will destroy during raining season as there is no breakwater to protect those community housing.

Figure 4; Uma sirak ne'e iha parte balun hanesan septic tank no didin balun estraga hotu.



Photo 4; Some part of the community housing, such as septic tank and in certain wall of the building are destroyed.

Figure 5. projetu emejensia ba ponte ne'ebe mak lokaliza iha Aldeia Asumaten lao fualn hat ona maibe seidak iha kontratu servisu tamba ne'e mak kompania para hela la halo servisu ho seriu no oras ne'e para hela.



Photo 5; a bridge construction that categorized as emergency project in Asumaten sub-village has been interrupted for four months because of the contract has not exist yet. The company has stopped to continue the construction.

